Geomorphology / geotechnical:	**Highly modified site** **Uniformly reactive clays to below construction depths**
Contaminations:	**Analytes all below health-based investigation levels of NEPM** **No known tipping activity**
Vegetation:	**(*as shown - refer text for discussion of extent and conservation of these communities and species on balance of Airport site*)**
Fauna:	**No habitat confirmations (*refer text for discussion of potential*)**
Heritage:	**Natural - None** **Indigenous - None identified (*Would only be shown on a need to know basis in any event. Refer text for discussion of management during construction*)** **European - None**



Figure 9

Existing conditions on the development site